



Fixture Supports built by Jay R. Smith Mfg. Co.

Standard to Labor Saver® Fixture Support Cross Reference Chart

Standard Support
Figure Number

Labor Saver®
Figure Number

| | |
|---------|---------|
| 0629 | 0609 |
| 0630 | -0610 |
| 0634 | 0614 |
| 0635 | -0615 |
| 0636 | 0616 |
| 0637 | -0617 |
| 0642 | 0622 |
| 0643 | -0623 |
| 0644 | 0624 |
| 0648 | -0628 |
| 0700 | 0710 |
| 0700D | -0710D |
| 0700-27 | 0710-27 |
| 0700E | -0710E |
| 0700DE | 0710DE |
| 0700Z | -0710Z |
| 0702 | 0712 |
| 0750 | -0760 |
| 0750D | 0760D |
| 0751 | -0761 |
| 0751D | 0761D |
| 0752 | -0762 |
| 0752D | 0762D |
| 0800 | -0801 |
| 0800D | 0801D |
| 0830 | -0831 |
| 0913 | 0923 |
| 0914 | -0924 |
| 0915 | 0925 |